



HELPDESK SBGUIDANCE

2018



RAVEN



HELPDESK SBGUIDANCE

2017



RAVEN



Signal



Error Messages



Steering





FAQ

MAIN MENU

RAVEN

1. Check GPS modus, you can find this at the right top button in the screen



SIGNAL




RAVEN

1. Choose the right type of antenna



Septentrio



NO GPS



RAVEN

1. Follow the next steps to find out what the problem is

Make sure the tractor is outside, the antenna has a clear view and is mounted on the roof of the tractor.



1. Check cabling

2. Replace antenna & cable

3. Set up GPS receiver

4. Measure terminal connector




SEPTENTRIO



RAVEN

1. Check if the antenna cable is connected with the antenna. Choose the right type of terminal and look where the antenna cable needs to be connected. GPS1 = tractor GPS2 = implement



Solved →

Not solved →

←  CHECK CABLING



1. Visual control antenna cable
2. Rusty?
3. Inner pin skewed?

TWIN steering → change GPS antennas to check

4. Replace antenna cable and antenna.

Solved

Not solved



REPLACE ANTENNA & CABLE



1. When you are sure the antenna and antenna cable are in order, the GPS receiver can be reset.

Open the Configurator and GO to Interfaces → GPS → Septentrio Receivers.
Select the right receiver, port and baudrate. Press on Connect.

Choose at Channel configuration Single or Multi.

Choose the right type of Diff. corrections, RTCMv3.0 or CMR


Press on Setup as Rover

Wait till Command queue is on 0.

Press on SBF (single-antenna) for one antenna

Press on SBG (multi-antenna) for two antenna's

Setup for Septentrio AsteRx4 Viper 4(+) →



Solved →

Not solved →





SET UP GPS RECEIVER



RAVEN

1. Measure the GPS connector at the terminal, this should be 5V. When there is no 5V the terminal must be repaired at Raven Europe.

Solved



MEASURE TERMINAL CONNECTOR



RAVEN

1. Choose the way the corrections should be received



Base station

GSM modem
(Geoconnect, Slingshot)



NO CORRECTION SIGNALS



RAVEN

1. Choose the type of modem



GSM MODEM



1. Follow the next steps to find out what the problem is.



1. Check cabling

2. Settings



GEOCONNECT



RAVEN


1. Antenna connected?
2. Power cable connected?
3. Ethernet cable connected?

- Viper 4 adapter harness, Dico In & Dico Out connected?
- Viper 4 terminal harness, RTK-COR & COM5 connected?

4. Led Power is on?
5. GSM antenna has a clear view?
6. Unscrew the cap and remove the SIM card, clean the card and the housing and replace the SIM card.

Solved

Not solved



CHECK CABLING



RAVEN

1. No/bad internet
 - Settings correct? Settings > GPS > Modem > Geoconnect > Change settings
2. Change internet mode 2G or 3G
3. Provider malfunction?
4. Move-RTK button must be green and receiving frames must raise to receive correction signals
 - If not, try MoveRTK Backup or another correction profile by pressing the sprocket wheel button

GeoConnect 3G

SIM 1	SIM 2
Land: NL	AT
Netwerk provider: KPN	AT (Mobile)
Eigen invoer:	<input checked="" type="checkbox"/>
APN: internet	
Gebruikersnaam:	
Wachtwoord:	
PIN: 0000	0000
Band selectie: AUTO	AUTO

Solved


Modem

RADIO GEOCONNECT NTRIP

MoveRTK
MoveRTK Backup
RADIO

Bytes received: 50,3 KB Time online: 00:02:29
Bytes sent: 1,3 KB Receiving: 2768 bps

NTRIP automatisch starten



SETTINGS



1. Follow the next steps to find out what the problem is



1. Check cabling

2. Settings Terminal

3. Settings Portal



SLINGSHOT



RAVEN

1. Press on the magnifier to take a closer look on the cabling.

2. Some notes:

- Antenna's connected? 2x Laird 1x patch antenna
- Power cable connected?
- Ethernet cable connected?

- Viper 4 adapter harness, Dico In connected to SlingShot modem?
- Viper 4, RTK-COR connected to SlingShot modem?



3. Slingshot is on?


4. Antenna's have a clear view?

5. Field hub 1: take out the SIM card, clean the card and the housing and replace the SIM card.



Solved


Not solved




CHECK CABLING




RAVEN





Viper 4 / 4+



Viper 4 / 4+ with Adapter harness



Geostar 200/250



CHECK CABLING



1. Settings correct?
 - Start the SlingShot Manager and connect to the modem, press on the question mark. Be sure the right data is used.
 - No Username and Password must be filled in here.
 - Baudrate always on 19200
2. Change internet mode 2G, 3G or 4G (at SlingShot Field Hub 2.0) (Change "Band")
3. Provider malfunction?
4. Move-RTK button must be green in SBGuidance (Settings > GPS > Modem > NTRIP). If not, try MoveRTK Backup profile.

Country:	NL
Network Provider:	KPN
APN:	internet
Username:	
Password:	
Mode:	0:Automatic
Band:	00:All Bands
Roam:	0:Roaming disable
Baudrate:	19200

Solved →

Not solved →

KPN


APN: internet
 Username:
 Password:

MoveRTK

APN: m2m-gps
 Username:
 Password:

Vodafone particulier

APN: live.vodafone.com
 Username: vodafone
 Password: vodafone



SETTINGS TERMINAL



1. Fill in the IMEI number at Manage > Field Hubs > Field Hub ID
2. Press Search
3. Press on the Field Hub
4. Check Field Hub Status, this must be Green and Ignition ON
5. Press on Correction Profiles and see if there is a Profile activated. Press on the pencil to check the settings of the Profile such as Username and Password.
6. Press on Telematics and see if there is a GPS location. If not, the Patch antenna is not connected or broken.
7. Press on View Last Reports and/or View CORS Diagnostics. Check if the system is connected with a network.

[View Last Reports](#) | [View CORS Diagnostics](#)

Solved



SETTINGS PORTAL



RAVEN

Telematics per Field Hub



Displaying 1 to 250 of 10000 result(s) for:356853054377629


Event	IGN	Latitude	Longitude	Alt (ft)	mph	Dir	RSSI	Service	Carrier	Roam	GPS Time	Server Time	Battery	IP	Owner
30	0	52.82625	4.71967	-12.47	0	36	-64	LTE	KPN	0	2017-11-09 15:41:37	2017-11-09 15:41:37	13.49	62.133.84.59	SBG Precision Farming map
30	1	52.82625	4.71967	-11.81	0	36	-64	LTE	KPN	0	2017-11-09 15:41:07	2017-11-09 15:41:08	14.43	62.133.84.59	SBG Precision Farming map
30	1	52.82625	4.71969	-8.2	0	36	-64	LTE	KPN	0	2017-11-09 15:40:36	2017-11-09 15:40:38	14.43	62.133.84.59	SBG Precision Farming map
30	1	52.82616	4.71989	-3.61	0	36	-64	LTE	KPN	0	2017-11-09 15:40:06	2017-11-09 15:40:08	14.39	62.133.84.59	SBG Precision Farming map
30	1	52.82611	4.72007	-9.84	5.59	36	-57	LTE	KPN	0	2017-11-09 15:39:35	2017-11-09 15:39:38	14.39	62.133.84.59	SBG Precision Farming map

CORS Diagnostics for 356853054377629 Source: localhost



Displaying 1 to 150 of 45932 result(s) for:356853054377629

Time	Network	Message	IP	Host	Port	Mnt Pnt	Username	PW	Server	Lat	Long	GGA
2017-11-09 15:41:48	MoveRTK (NL)	Running: 08:21:59	62.133.84.59	ntrip.movertk.nl	2101	VRS_GG_RTCM3.0	mrsalm01	8301 nnn2	52.82625	4.71967	\$GPGGA,144037.0,5249...	
2017-11-09 15:40:27	MoveRTK (NL)	Running: 08:20:38	62.133.84.59	ntrip.movertk.nl	2101	VRS_GG_RTCM3.0	mrsalm01	8301 nnn2	52.82616	4.71989	\$GPGGA,143937.0,5249...	
2017-11-09 15:40:07	MoveRTK (NL)	Running: 08:20:18	62.133.84.59	ntrip.movertk.nl	2101	VRS_GG_RTCM3.0	mrsalm01	8301 nnn2	52.82611	4.72007	\$GPGGA,143907.0,5249...	
2017-11-09 15:39:46	MoveRTK (NL)	Running: 08:19:57	62.133.84.59	ntrip.movertk.nl	2101	VRS_GG_RTCM3.0	mrsalm01	8301 nnn2	52.8255	4.71993	\$GPGGA,143837.0,5249...	
2017-11-09 15:39:06	MoveRTK (NL)	Running: 08:19:17	62.133.84.59	ntrip.movertk.nl	2101	VRS_GG_RTCM3.0	mrsalm01	8301 nnn2	52.82474	4.71892	\$GPGGA,143807.0,5249...	



SLINGSHOT PORTAL



1. Choose the way the corrections should be received



BASE STATION (RADIO)



RAVEN

1. Follow the next steps to find out what the problem is.



1. Check cabling

2. Check settings

3. Other



BASE STATION





1. Check if the radioantenna cable is connected with the radioantenna. Choose the right type of terminal and look where the radioantenna cable needs to be connected.



GeoStar 200 / 250



Viper 4 / 4+



CHECK CABLING



1. First check if "Enable internal SATEL radio" is on. You can find this setting at Setup > GPS > Modem.
2. Go to the Base Manager.

The ideal situation is shown in the figure.

The Base Station is less than 10 kilometers away, and the terminal is connected with it. (green sign)

If not connected (red or orange) select a station and press on the two red connectors.

If the system doesn't connect, try another Base Station.

Check the settings of the Base Station by selecting the station and press the tool button.

Modem

RADIO GEOCONNECT NTRIP

Enable internal SATEL radio

ID	Naam	Afstand	Verbonden
1	MIDDENMEER	27 m	●
2	ANNA-PAULOWNA	12,41 km	●
12	ZWAAGDIJK	15,56 km	●
4	HEERHUGOWAARD	17,07 km	●
5	WARMENHUIZEN	20,41 km	●
6	URSEM	21,92 km	●
13	AKERSLOOT	30,52 km	●
3	OOSTEREND	33,51 km	●

Status: -

GPS tijd: 08:47:52
Positie: 52° 48' 36,69 N
005° 00' 26,06 E
-2,83 m
CPU load: 40%
Sattellieten: [Progress bar]

Base ID: 1
Diff.Corr.: CMR
Baseline: 28,95 m
Ratio: 100%
Ontvangen: 226
Laatste bericht 1 sec geleden


Radio: [Progress bar] -51 dBm

v3.3 XML - 2013-02 ● GPS ● BASE ● SATEL

SBG PRECISION FARMING

Solved

Not solved



CHECK SETTINGS



1. When the system doesn't connect with any Base Station and the radio signal is -118 dBm replace the radio antenna and/or cable.
2. If the settings are correct and the radio antenna is connected call Raven Europe to ask if there is something wrong with the Base Station.
3. When the settings are correct and the radio antenna is not the problem there could be something wrong with the terminal.

Solved



OTHER



RAVEN

1. Check if the radioantenna cable is connected with the radioantenna. Choose the right type of terminal and look where the radioantenna cable needs to be connected.



GeoStar 200 / 250



Viper 4 / 4+

Solved




Not solved



CHECK CABLING ON TERMINAL






RAVEN



ERROR MESSAGES



1. Check at Info > CAN > second tab if ACT Power is around 14V. If ACT is 0 check relays, fuses and cabling.
2. ACT is around 14V try another STU.
3. Replacing the STU by another one can indicate that the STU is broken.




ERROR MESSAGES



1. The system should work with RTK-GPS but the system is not in RTK modus at the moment.

Find out what the problem is:

No correction signal



ERROR MESSAGES



1. The system should work with RTK-GPS but the system is not in RTK modus at the moment.

Find out what the problem is:

No GPS signal




ERROR MESSAGES



No communication with DynamiQ.

1. Check relays, fuses and cabling.
2. Check the CAN connector at the terminal.
3. Switch off the terminal and measure the CAN resistance on the green and yellow wires at the DynamiQ and STU (grey Deutsch connector)
 - Implement Ready without implement 120 Ohm
 - Implement Ready with implement 60 Ohm
 - Basic Harness 60 Ohm
4. Replacing the DynamiQ by another one can indicate that the DynamiQ is broken.





ERROR MESSAGES



1. If there is a problem with steering in combination with SBGuidance follow the next steps to find out what the problem is. First choose where the problem is, tractor steering or implement steering.

Make sure all the offsets are correct! You can find the offsets at Settings > Offsets.



STEERING




RAVEN

1. Choose the type of steering system the customer is using.

Examples of a Steer Ready are:

- Fendt VarioGuide
- New Holland IntelliSteer
- Massey Ferguson AutoGuide
- John Deere AutoTrac Ready
- Claas ATP Ready
- Deutz Fahr AgroSky
- Valtra AutoGuide



Non Steer Ready
(SBG/Raven Manifold)




TRACTOR STEERING



RAVEN

1. Choose the topic that most closely relates to the problem



Steering too aggressive

Tractor is only steering to one side

Steering too slow


Disengage problems

Tractor is swinging

Intentionally left blank for your own information

Tractor drives next to the line

Intentionally left blank for your own information



NON STEER READY




RAVEN

Gain too high

Tractor is driving like the pictures right.

1. Lower the value of the Gain.
2. If it is not getting better you can also check the minimum steering values.



STEERING TOO AGGRESSIVE




RAVEN

Gain too low

Tractor is driving like the pictures right.

1. Raise the value of the gain.
2. If it is not getting better you can also check the minimum steering values.






STEERING TOO SLOW




RAVEN

1. Try to find out where the problem is:

- Steering can be too aggressive:  Steering too aggressive
- Steering can be too slow:  Steering too slow
- Wheel angle sensor problem:  Wheel angle sensor

At all times: be sure the configuration of the steering controller in the CANTool is as good as possible! That means:

- Left, right and center values of wheel sensor correct
- Min. and max. steering values correct
- Propotional gain correct value



TRACTOR IS SWINGING



RAVEN




1. Probably the center of the wheel angle sensor has a wrong value. Drive manually a straight line and see what the center position should be. Change the value and try again.

Change the value of the wheel center in the next screen:

You will find the disengage setting in SBGuidance at Setup > Vehicle > button gearwheels at the right bottom side > next page

2. Make sure there is no virtual implement ('purple machine') mounted with a D-offset!


Go to Setup > Vehicle > Offsets to change the D-offset



TRACTOR DRIVES NEXT TO THE LINE



1. Check the voltage of the wheel angle sensor. When the sensor is broken, the voltage is 0 and the system only wants to steer to one side.
2. Go to the CANTool in the configurator and go to the settings page of the steering values. Press on the Test buttons and see if you press for example Left the wheels turns to the left. If not, place a checkmark at Invert L/R.
3. Check if Left and Right is working correctly.



TRACTOR IS ONLY STEERING TO ONE SIDE



RAVEN

1. Automatic steering disengages too easy?
 - Raise the disengage value
2. Disengaging automatic steering is too hard?
 - Lower the disengage value

You will find the disengage setting in SBGuidance at Settings > Vehicle > button gearwheels at the right bottom side > next page





DISENGAGE PROBLEMS



In some cases the tractor can be swinging around the guidance line because of a problem with the wheel angle sensor. Figure out if the wheel angle sensor is working correctly:

1. Go to Settings > Vehicle and press on the gearwheels button at the right bottom side. Go to page 2
2. Now you see the actual value and the saved values of the sensor for left, centre and right.
3. Turn the steering wheel completely to the left and check if there is a voltage behind actual voltage. It should be something around 1-1,5 V
4. Now turn the steering wheel slowly to the right, and check if the actual value rises. There must be no gaps! (0 V) When the steering wheel is completely to the right the actual value will be around 4-4,5 V. The mentioned values for left and right can also be opposite.

If there are gaps (0 V) there is something wrong with the wheel angle sensor or the cable. Check the cable and sensor visually. You can disconnect the disk of the sensor and clean it. Replacing the sensor and/or cable can also declare the problem.



WHEEL ANGLE SENSOR PROBLEM



I have no GPS, what is wrong?

First try to find out what the problem is, no GPS or no correction signals.

Steering controller not ready, what is wrong?

DynamiQ not available, what is wrong?

GPS is not working well, accuracy higher than 1-2
cm, what is wrong?

First try to find out which setting you need to change for a better result.



FAQ



RAVEN

