

# Cruizer II™ and Cruizer II™ RTK Software Update Details

Version: 3.4.1

Release Date: 02/06/15

NOTICE: Do not install Cruizer II software on a Cruizer.

DO NOT remove power or the USB drive from the Cruizer II at any time during the update process. Removing power or the USB drive during the update may result in corrupted program files, and would require assistance from Raven service to resolve.

Since the USB drive may bounce around while the vehicle is in motion, it is recommended to remain stationary while the update is in progress. This will help ensure that the update process is not interrupted.

This function allows you to update the software for the Raven Cruizer II. This may be done whenever there is a new software version available. You must have the software update stored on a USB storage device prior to beginning the update. To do this, copy or download the update to the root directory of the USB storage device.

NOTE: The file is in a zip format and needs to be uncompressed before using. Unzip the files directly to the root directory of the USB storage device.

**\*\*DO NOT PUT THE FILES INTO A SUB-FOLDER ON THE STORAGE DEVICE.**

## Download and Installation Instructions

This function allows you to update the software for the Raven Cruizer II. This may be done whenever there is a new software version available. You must have the software update stored on a USB storage device prior to beginning the update. To do this, copy or download the update to the root directory of the USB storage device.

NOTE: The file is in a zip format and needs to be uncompressed before using. Unzip the files directly to the root directory of the USB storage device.

**\*\*DO NOT PUT THE FILES INTO A SUB-FOLDER ON THE STORAGE DEVICE.**

Cruizer II download instructions for Self Extracting Application:

1. Download (Save As) file to a Location on your computer
2. Unzip/Extract Saved File to Root Directory of USB
3. Using Mouse left click twice on Self Extracting Application on Root Directory of USB
4. Select Root Directory of USB as Location to Extract

For questions about storing the new software on your USB storage device, contact your Raven distributor or Raven Technical Service Specialist at 1-800-243-5435.

## Release Notes

Enhancements and Defects Resolved:

- Changes to support upgraded MS53 processor
- SHP file change to point format for yield jobs
- Fix for VRA jobs not closing correctly
- Changes to support faster/wider swathing
- Compatibility changes for reverse detection with SmarTrax
- Change to validate old job data prior to starting a new job (addresses memory issues from abruptly closed jobs)
- Extra decimal precision added to highest resolution swath offset setting
- Added GPS shield selection for external Slingshot/Satellite GS receivers