

# AutoBoom® Software Update Details

Version: 5.03.02

Release Date: 07/10/15

Previously, AutoBoom nodes could be updated through a serial interface cable P/N 115-0230-011 or through a Raven field computer. This release of AutoBoom software does not include a serial update interface. The current version of AutoBoom software will need to be loaded through a Raven field computer or a Raven Service Tool P/N 117-0171-464. Damage may be caused to the node if the serial update cable is used.

## Release Notes

- Fixed alarm count issue with Viper 4
- Fixed alarm clearing problem after condition is resolved