

AutoBoom® Software Update Details

Version: 5.04.01

Release Date: 11/09/16

Previously, AutoBoom nodes could be updated through a serial interface cable P/N 115-0230-011 or through a Raven field computer. This release of AutoBoom software does not include a serial update interface. The current version of AutoBoom software will need to be loaded through a Raven field computer or a Raven Service Tool P/N 117-0171-464. Damage may be caused to the node if the serial update cable is used.

Release Notes

- Updated the Case IH 2240/2250 tuneset; now named Case IH 2230/40/50 and changed several parameters