MULTI-SECTION CHECK VALVE ASSEMBLY


REQUIRED TOOLS

- Thread Sealant
- Wrenches

CHECK VALVE ASSEMBLY

1. Apply PTFE thread sealant to all threaded joints.

FIGURE 1. Multi-Section Check Valve Assembly



- 2. Install the relief valve into the top port of the check valve.
- 3. Install the bleed valve into the bottom port of the check valve.

NOTE: When installing the 1/4" bleed valve, make sure the vent hole is not directed towards the face.

FIGURE 2. Installed Check Valve Assembly

