

CR7™ and CR12™ Software Release Notes

CRX Version 23.4.0.97

Features

- Added the ability to detach tramlines from the normal swath pattern for farmers with an irregular sprayer width.
 - This feature can be found under the 'Tramline Setup' menu within operation planning.

Enhancements

- General UI/UX improvements.
- Removed the Wi-Fi icon from the top-bar to increase clarity.
- Improved the algorithm when using implements with many sections, increasing performance.
- Changed the database to use SQLite for increased performance of data handling.
- Added clarification when steering is not available by pressing on the steering widget.
- Added persistence of the input default rate so this can be used again in following jobs.
- A minimum guidance width of 0.01m is now required.
- Greatly improved the speed of opening the keyboard.
- Greatly improved the speed of opening the numpad.
- Product names now support special characters.

Defects Resolved

- Fixed multiple translation errors.
- Fixed issue where the machine reference point did not always work.
- Fixed issue where field boundaries were not properly generated after a corner flag recording.
- Fixed issue where the Wi-Fi receiver on the CR7 could malfunction by providing an external Wi-Fi receiver.
- Fixed issue where baselines in an operation plan could change from straight to curved.
- Fixed issue where the software update of hardware components would not be listed.
- Fixed issue where coverage would switch quickly when entering a job.
- Fixed issue where lines would be centered on the machine reference point instead of the machine center.
- Fixed issue where switching layers would take a very long time.