

# SmartRow™ Software Update Details

Version: Cruiser 1.10.0001

Release Date: 01/31/12

## Download and Installation Instructions

If you are using the SmartRow console cable, disconnect the 9-pin connector from the back of your product control console (i.e. SCS 440 or 4400) and connect it to a serial port on your computer.

\*If you are not using the SmartRow console cable, you can use the DGPS cable with a null modem adaptor.




\*\*If you are using the SmartRow console cable connected to the Console port on the back of your SmartRow controller, go to the "Console Port" screen in the "System Config" menu and change the setting to NONE.

Use the appropriate "UpgradeComX.bat" file where X matches your com port. If there is not a file for the com port you are using, copy one of the existing files and change the number to match your port.

Make sure the update completes successfully. If the update fails or times out, cycle power to the SmartRow controller and retry the update.

Once the update has been applied successfully:

- a) Reset the Console Port to Port C if you changed it in Step 1.
- b) Reconnect the console or DGPS cable to the product control console.

Press  and  at the same time to enter the diagnostics menus. Press  twice and verify that the SmartRow version number matches the newest version applied.

## Release Notes

Fixes 4600 connection issue.