

AUTOBOOM® XRT SOFTWARE RELEASE NOTES

VERSION 20.3.3.52

KEY FEATURES, IMPROVEMENTS AND BUG FIXES

- Ground mode performance improvements
- Canopy mode performance improvements
- Updated height sensor software to version 1.22 to improve spray drift suppression
- Controls update to improve boom response if the system voltage varies
- Improved CAN address arbitration if there is a device already claiming the preferred source address
- Improved metering of diagnostic messaging requests
- Improved height sensor reprogramming reliability
- Allow joystick switches to be pressed prior to machine type selection
- Updated object pool, machine database and code to support new machines
 - Bruin 120' Pommier
 - RoGator A and B Series
- Disabled IMU updated needed alarm
- Fixed bug that can cause outer sensors to report falsely high readings after unfolding
- Fixed Canopy mode switching to Ground after power cycle and engage with joystick