

CNH SC1 22.3.2.5 SOFTWARE RELEASE NOTES

ENHANCEMENTS

- Software updates to enable up front filtering of the GNSS stream
- Enables logging support to review the GNSS signal at the front end of the algorithm
- RS1 factory default of Ethernet to a DISABLED state
- Support for new hardware
 - OEM729
 - Ethernet PHY

RESOLVED DEFECTS

- Reverse Heading Jump defect resolved