

1/4" STAINLESS STEEL CONTROL VALVE REPLACEMENT PARTS

063-0159-808

ITEM	DESCRIPTION	RAVEN PART #
1	Motor Assembly	063-0159-619
2	Bracket	107-0159-668
3	Valve	334-0001-028
4	Coupler	107-0159-669
5	1/4-20 UNC x 1/2" Socket Hd. Cap Screw	311-0068-064
6	10-24 x 3/8" Socket Hd. Cap Screw	311-0068-047
7	#10 Lockwasher	313-1000-036
8	Cover (Blue)	106-0159-444
9	Clamp, U-Band	435-3003-037

NOTE: Reverse Polarity Jumper Cable is no longer needed with this valve; 063-0159-808, Revision D or higher.

