

3" STAINLESS STEEL CONTROL BUTTERFLY VALVE REPLACEMENT PARTS

063-0159-911

ITEM	DESCRIPTION	RAVEN PART #
1	Butterfly Half (Tapped)	107-0159-701
2	Butterfly Half (Counter Bored)	107-0159-700
3	Seal	219-0000-068
4	#8-32 x 1/2" Cap Screw	311-0068-176
5	Valve Body	107-0159-703
6	O-Ring, Viton	219-0000-026
7	#10 Lock Washer	313-1000-036
8	#10-32 x 3/8" Cap Screw	311-0068-177
9	Stem	107-0159-702
10	Motor Assembly	063-0159-619
11	Cover (Blue)	106-0159-444
12	Bracket	107-0159-666
13	#10-32 x 5/8" Cap Screw	311-0068-181
14	Clamp, U-Band	435-3003-037

NOTE: Reverse Polarity Jumper Cable is no longer needed with this valve;
063-0159-911, Revision C or higher.

